

TECHNICAL ADVISORY

CDS universal Driveshaft Refurbish Program

Reported Issue: 000-150-174 CDS driveshaft New – obsolete*** 000-150-174R refurbished units field support

Applicable Models: 2008-2022 CDS 4.8 / CDS 4.8SV

The purpose of this document is for general information only. Normal warranty provisions apply.

Technical Advisory Safety Rules

Failure to obey the instructions and safety rules in the appropriate Operator's Manual and Service Manual for your machine may result in death or serious injury. Many of the hazards identified in the operator's manual are also safety hazards when maintenance and repair procedures are performed.

Do Not Perform Maintenance Unless:

- You are trained and qualified to perform maintenance on this machine.
- You read, understand and obey manufacturer's instructions and safety rules
- You have the appropriate tools, lifting equipment and a suitable workshop.

The information contained in this document is a supplement to the service manual. Consult the appropriate service manual of your machine for safety rules and hazards.

Background:

Due to material shortages the 150-174 NEW universal 39-44" DBSE shaft is no longer available

Procedure: Field replacements are a 000-150-174R 39-44" DBSE – Refurbished unit. We support returning the core shafts to have them refurbished to provide field support for damaged or broken shafts.

000-150-174R – Refurbished driveshaft 39-44" DBSE universal Core charge – \$100.00 on old unit until it is returned All shafts purchased for stock will have this core charge until a damaged unit is returned for rework – core can then be refunded on invoice.

This completes the steps necessary for this advisory.

1500 Industry St. Suite 300, Everett, WA Phone: (425) 775-7272 TECHSUPPORT@HYDRAMASTER.COM