

De-Foam™

Powdered Defoaming Additive



- » When sprinkled on the carpet, **De-Foam** breaks down foam before it gets to your machine.
- » Unlike some liquid defoamers that leave a sticky residue behind, **CleanMaster De-Foam** is a residue free formula.
- » **De-Foam** breaks down existing foam residue which makes your vacuum recovery more efficient and keeps your waste tank from prematurely filling up. It prevents foam from forming in wands and hoses.

If for any reason you are not thrilled with the performance of De-Foam return it to your distributor and we'll get you a product that does.



Directions:

1. Always pre-test all cleaning solutions in an inconspicuous area for colorfastness prior to application.
2. Apply small amount of water to carpet and agitate to determine the presence of foaming residue.
3. To reduce foam build-up in waste tank, add one ounce of **De-Foam** to your waste tank before the job starts.
4. To reduce foam build-up in vacuum recover hoses directly, sprinkle 1 ounce of powder into vacuum hose at the cleaning wand end and let the vacuum pull the solution through the hose.
5. For severe foam issues in the carpet, sparingly spread, broadcast or "chicken feed" **De-Foam** over entire carpet.
6. Increase or decrease the amount as needed to eliminate foam.
7. Proceed to clean in normal manner.

See the material safety data sheet at www.cleanmaster.com for safety and regulatory information.

Learn more,
scan here



Available in: 6.5 Pound Jar; Case of 4 x 6.5 Pound Jar
Part number: 950-177-S, B

11015 47th Ave W, Mukilteo, WA 98275

www.cleanmaster.com • 877.282.2319

CLEANMaster



CLEANMaster
HydraMaster Cleaning Solutions