



Date: 7/01/13

Dear HydraMaster Equipment Owner,

Included in this mailing is important information concerning your HydraMaster equipment. HydraMaster will at times correspond with you directly about important safety, reliability, or performance issues. Please take the time to read the correspondence carefully and take the necessary actions.

If you own more than one piece of HydraMaster equipment, multiple copies of the Product Support Bulletin (PSB) may be included along with a list of the serial numbers that this PSB applies to. After considering the content of the PSB, insert it into your equipment owner manual for future reference.

If you have any questions concerning this correspondence please contact your HydraMaster Customer Service Representative at the number listed below or visit our website at [www.hydramaster.com](http://www.hydramaster.com).

Thank you for choosing HydraMaster as your source for professional cleaning products



## Product Support Bulletin

To:	HydraMaster Customer		
Document #:	PSB-46006	Effective Date:	Jul 1, 2013
Title:	<b>CDS 4.8 Salsa Exhaust Hose</b>		

The 3” formed rubber hose used in the CDS exhaust system was changed in September 2012 due to supplier quality issues. We recently discovered that some units shipped from HydraMaster between September 2012 and April 2013 may have contained the older hose in the install kit. The hoses can be identified as follows:

- There are two of these hoses, both located behind the vans driver’s seat. One on the inlet to the Salsa heat exchanger, between the blower and the Salsa unit. The other is on the opposite side of the heat exchanger (outlet).
- The correct hose is a Goodyear hose that can be identified by the engraved description in the hose “AUDY >EPDM< 13031A”
- The incorrect hose is made by Gates, it will either have “1ZF14XJM” printed on it or nothing at all.

Due to the potential for failure and damage to other components we ask that you please inspect the inlet and outlet hose on your CDS unit to verify that it has the correct hose. If your unit is equipped with the incorrect hose, or you cannot easily identify the markings on the hose, please contact your local HydraMaster distributor for assistance.