
TECHNICAL BULLETIN

Replacement of tachometer gauges 000-074-034 and 000-074-178 with 000-074-187

Models Affected: All CDS units

The purpose of this document is for general information only. Normal warranty provisions apply.

Technical Bulletin Safety Rules

Caution

Failure to obey the instructions and safety rules in the appropriate Operator's Manual and Service Manual for your machine may result in death or serious injury. Many of the hazards identified in the operator's manual are also safety hazards when maintenance and repair procedures are performed.

Do Not Perform Maintenance Unless:

- You are trained and qualified to perform maintenance on this machine.
- You read, understand, and obey manufacturer's instructions and safety rules.
- You have the appropriate tools, lifting equipment and a suitable workshop.

The information contained in this tech tip is a supplement to the service manual. Consult the appropriate service manual of your machine for safety rules and hazards.

Background:

Hydramaster will begin using a new 0-4000 RPM tachometer (PN:000-074-187) gauge on all CDS units starting April 1st, 2021. The new tachometer will replace 000-074-034 and 000-074-178, which have been used on various CDS machines over the past several years.



Going forwards Hydramaster will only stock 000-074-187. For units manufactured prior to April 1st, 2021; built with 000-074-034 and 000-074-178, product support kit 000-078-982 along with installation instructions has been created (available to order shortly) to accommodate this change.