

TECH TIPS

Guardian Couplers – HydraMaster Slide-in Machines 039-060/039-061

Models Affected: TITAN 425 - BOXXER XL – TMTG4000 Truckmount to Go



The purpose of this document is for general information only. Normal warranty provisions apply.

Tech Tips Safety Rules

Caution

Failure to obey the instructions and safety rules in the appropriate Operator's Manual and Service Manual for your machine may result in death or serious injury. Many of the hazards identified in the operator's manual are also safety hazards when maintenance and repair procedures are performed.

Do Not Perform Maintenance Unless:

- You are trained and qualified to perform maintenance on this machine.
- You read, understand, and obey manufacturer's instructions and safety rules.
- You have the appropriate tools, lifting equipment and a suitable workshop.

The information contained in this tech tip is a supplement to the service manual. Consult the appropriate service manual of your machine for safety rules and hazards.


HydraMaster is refining the couplers used on some slide in machines and for easier field replacement parts:

000-039-060: Guardian Coupler 7/8" x 1" Bore - 18/23HP (TITAN 425, TMTG4000)

000-039-061: Guardian Coupler 7/8" x 1-1/8" Bore - 31HP (BOXXER XL)

000-152-015: Guardian Rubber Element Sleeve – Series 86SF Replacement

Clean metal prior to installation, to remove all nontoxic, nonflammable mineral oil rust inhibitor.



11015 47th Ave W. Mukilteo, WA
PHONE: (425) 775-7272
www.hydramaster.com

TT-47850
Page 1 of 1