



Date: 5/25/11

Dear HydraMaster Distributor,

Included in this mailing is important information concerning HydraMaster equipment. Please take the time to read the correspondence carefully and take the necessary actions.

If applicable and our serial number database indicates that you are in possession of more than one piece of affected equipment, multiple copies of this Product Support Bulletin (PSB) will be included along with a list of the serial numbers that this PSB applies to. **Please make every effort to distribute these copies to the appropriate owners as soon as possible if the PSB calls for it.** At the same time please contact HydraMaster with the current ownership information for the serial number(s) that you no longer have in your possession. After reviewing the content of the PSB, please insert a copy of it into the appropriate equipment manual(s) you have on file, for future reference.

If you have any questions concerning this correspondence, please contact your HydraMaster Customer Service Representative at the number listed below or visit our website at www.hydramaster.com.

Thank you for choosing HydraMaster as your source for professional cleaning products!

HydraMaster (P) 800.333.4757 (F) 800.426.4225



Product Support Bulletin

To:	All HydraMaster Distributors		
Document #:	PSB-44344	Effective Date:	May 25, 2011
Title:	Maxx 470 / CDS 4.8 Blower Kits		

A change in the manufacturing of the Tuthill 4007 blower has eliminated the threaded outlet on the blower. This change will require a new outlet adapter for the blower if it is replaced. We have created a kit that includes the blower and the new adapter to assure the necessary parts are provided when changing the blower.

Maxx 470

When ordering a replacement blower for a Maxx 470 instead of ordering 000-111-147, order part number **000-078-920**.

CDS 4.8

When ordering a replacement blower for a CDS 4.8 instead of ordering 000-111-147 or 000-078-503, order part number **000-078-925**.

If you have any questions please contact HydraMaster Technical Support at the phone numbers listed below.